

**AMUSEMENT RIDE COMPLIANCE REVIEW**

K-ISH 516 (Rev. 6-17)

☐ Temporary Ride      ☒ Permanent Ride      ☐ Non-profit/Municipality
Inspection date: 3/26/18 Name of KDOL auditor: Marla TunnesRide owner: Great Wolf Lodge Ride location: 10401 Cabella Drive KCKNumber of rides: 5Contact person: Daniel Terrazas Phone: 913-907-2963 Email: dterrzas@

YES NO

- |                                     |                          |  |
|-------------------------------------|--------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | 1. Valid permit and inspection decal affixed to each ride;   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | 2. The current certification of an inspector's qualifications to inspect amusement rides;  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | 3. The current certificate of inspection for each ride signed by a qualified instructor;   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | 4. Daily maintenance and inspection records for each ride;   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | 5. The amusement ride manufacturer's operational manual for each ride;   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | 6. The amusement ride manufacturer's nondestructive testing recommendations for each ride and results;   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | 7. The amusement ride manufacturer's inspection guidelines for each ride;  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | 8. Operator training records for each operator trained on each ride;   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | 9. Report of itinerary for the current year;   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | 10. Written certification that the ride meets the applicable ASTM international F24 committee standards;   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | 11. Signage must be posted at the point of admission or ticket sale and at least two other locations in close proximity to the amusement ride explaining a patron's duty to report injuries; |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | 12. Proof of insurance policy in effect at the time of operation of the amusement ride with certain coverage in place required by K.S.A. 40-4802 and;  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | 13. All safety instructions for the ride must be posted in plain view on or near the ride in a location where they can be easily read.   |

Great Wolf. Co-

Supplemental Compliance Review form (K-ISH 516-A) will detail any violation/violations marked **NO**, for each ride.

Note: All amusement ride records shall be grouped according to ride and shall be maintained by the owner for three years and kept at the location of the ride's operation.

This form reflects the observations at the time of review in accordance with the Kansas Amusement Ride Act. This is a compliance review, and does not certify the safety or integrity of the amusement ride itself, nor provide affirmation that the owner or operator is in full compliance with Kansas statutes and regulations.

Auditor signature: Marla Tunnes Date: 3/26/18On-site contact signature: Daniel Terrazas Date: 3/26/18

## AMUSEMENT RIDE COMPLIANCE REVIEW - SUPPLEMENTAL

K-ISH 516-A (Rev. 7-17)

☐ Temporary Ride ☒ Permanent Ride ☐ Non-profit/Municipality

Inspection date: 3/26/18 Name of KDOL auditor: Marlen Jones

Ride owner: Great Wolf Lodge Ride location: 10401 Gubela Drive, KCK

Number of rides: 5

Contact person: Daniel Terrazas Phone: 913-907-2963 Email: dterrazas@greatwolf.com

### COMMENTS:

On Saturday 3/24/18, 11 yr old male patron & similar aged friend were riding the triple twist in a 2 person raft. Bottom attendant, [REDACTED], observed both boys off of raft and patron holding his shoulder. He jumped in the water to assist. Father was contacted (was here w/ grandparents). Patron (Aide) received first aid. Father ok'd to receive no further treatment.

3/25 child [REDACTED] was playing in water park & then checked at [REDACTED]. Later on 3/25, Father of patron called GWL that child was still in pain & was taken for treatment & was diagnosed w/ a broken clavicle. At that time, ride was shut down.

After patron came out of raft, raft was inspected, and waterflow rates were checked. Everything checked at OK and since patron received no medical treatment

slide was re-opened. Another patron (unknown) went to the supervisor [REDACTED] and told her he overheard the patron & friend discussing trying to flip raft.